uL Error Code Balance Reset – OB2140 & OB2141

While balance is off, press and release the on/off button.

IMMEDIATELY press and hold the zero button. Continue holding until screen reads Ab5-0.

Balance will run through normal startup, displaying a few more codes. Once finished, balance should read zero and be ready for use.